



Forest Operations Coupe Plan

for

Harvest Unit 699-518-0005-A - Photo Finish

Upper Murray

699 - Boebuck

Location of coupe centroid

Easting/Northing: (GDA-94)	587521/5959497 Zone 55
VicGrid	2766650/2550657
Latitude/Longitude:	36° 30' 21" S/147° 58' 38" E

This Forest Operations Coupe Plan consists of the following five sections:

- Section 1 - Coupe Description
- Section 2 - Contractor Direction
- Section 3 - Occupational Health and Safety
- Section 4 - Coupe Management Actions
- Section 5 - Harvesting Commencement and Completion Declarations

Plan Preparation and Endorsement

Prepared By	Signed	Date
Peer Reviewed By	Signed	Date
Endorsed By	Signed	Date

End of Forest Operations Coupe Plan Front Page



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 1
 Contractor Section - Coupe Description

Descriptive Information		(also see Part 2: Coupe Map - Operation and Context)		
Forest type	Alpine Ash predominant			
Area of TRP Boundary	22.0			
Area of Harvest Unit (operational area)	12.3			
Regional Forest Agreement	NORTH EAST			
Forest Management Area	North East			
General aspect	Northerly			
Elevation	1240 meters			
Slope	Minimum 0°; Average 5°; Maximum 10°			
Proportion of the nett coupe area > 20°	0-10 %			
		Horizon A	Horizon B	Horizon C
Soil Erosion Classification		-	-	-
Soil Permeability Classification		-	-	-
Overall Soil Category		<i>High</i>	<i>High</i>	<i>High</i>
Rock cover exceeds 30% of nett area	No			

Estimated species and volumes			
Product	Grade	Volume	
Alpine Ash	B	360 m ³	
Alpine Ash	C	379 m ³	
Alpine Ash	D	285 m ³	
Alpine Ash	E	498 m ³	
Alpine Ash	H	2153 m ³	

End of Forest Operations Coupe Plan Section 1



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 2
 Contractor Section - Contractor Direction

Personnel	
VF Officer	
Contractor	
Operational Issues	
Silvicultural Intent	Adaptive Silviculture - Recovery
Silviculture system(s)	Clearfelling - Salvage
Recommended harvesting period	Shoulder of 2020-2021
Description of the coupe boundaries and method used to locate boundary in the field	Northern boundary is 40m hydrology buffer. Southern boundary is Walkers Road. Eastern boundary is 10m buffer on the Alpine National Park. Western boundary is 40m hydrology buffer/ adjacent coupe Dead Heat.
Operational constraints	All boundaries have been located using a GPS and Rangefinder. Marked in the field using blue flagging tape. Water Quality Risk is high or very high as per Post Bushfire Timber Recovery Instruction (2020).
Social Issues	
Identified social issues	
Coupe Access	
Proposed Access	Walkers Road
Proposed driveway length to construct	0
Proposed in-coupe road length to construct	100
Proposed in-coupe roading requirements	5D access road to central landing.
Proposed number of stream crossings	0
Proposed number of landings	1



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 2
 Contractor Section - Contractor Direction

Environmental and operational specification Standard

All operations to be conducted in accordance with the Code of Practice for Timber Production 2014 and VicForests Utilisation Procedures except where additional specifications or variations are specified below. Where there is no comment (ie the column is blank), it should be read '*No variation to the standard procedure*'.

Environmental & Operational Elements	Variations, amendments or additional instructions
--------------------------------------	---

Utilisation Procedures Section	
--------------------------------	--

	Planned silvicultural system and requirements
--	--

	Planned silvicultural system and requirements	As per HCV plan & Operations Map.
--	---	-----------------------------------

	Additional specifications, requirements or instructions
--	--

	Additional specifications, requirements or instructions	
--	---	--

5.	Coupe boundaries
-----------	-------------------------

5.1	Marking a coupe	Coupe has been marked using increased waterway and drainage line buffers and filters as per the Post Bushfire Timber Harvesting Guidelines.
-----	-----------------	---

5.2	Construction of boundary trails	Not required as a regen burn is not anticipated.
-----	---------------------------------	--

5.3	Location of Boundary Trails	
-----	-----------------------------	--

5.4	Converting boundary trail to fire trail	Not required as a regen burn is not anticipated.
-----	---	--

6.	Excluded areas
-----------	-----------------------

6.1	Activities in excluded areas	Snigging through retained areas or corridors may be permitted. Authorisation from the supervising forester is to occur prior if required.
-----	------------------------------	---

7.	Harvest requirements
-----------	-----------------------------

7.1	Retained Trees	As per HCV plan & Operations map. All live trees and non ash trees will be retained unless deemed unsafe.
-----	----------------	---

7.2	Large Tree Protection	
-----	-----------------------	--

7.3	Trees to be felled	Fire killed ash outside retained areas and trees not selected for retention.
-----	--------------------	--

Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 2
 Contractor Section - Contractor Direction

7.4	Stump heights	
7.6	Coupe utilisation requirements	
9.	Thinning requirements	
9.2	Trees to be retained	
9.3	Thinning method	
9.4	Damage	
10.	Extraction tracks within coupes	
10.1	Location of Extraction Tracks	Minimise snig track network. Plan snig tracks to comply with Post Bushfire Timber Harvesting guidelines with particular regard to drainage and minimising sediment runoff. Rehabilitate tracks and install drainage management works progressively, where possible.
10.2	Blading-off	
10.3	Drainage and rehabilitation	
10.4	Snigging on roads	
10.5	Stream crossings	
12.	Landings	
12.1	Location of landings	Bark can be used as sediment runoff control. Bark may be positioned with a view to burning near landing.
12.2	Construction and maintenance of landings	
12.5	Bark disposal	
12.7	Rehabilitation	
13.	Road and construction maintenance	
13.2	Location, design and period of construction	
13.4	Grade	
13.5	Clearing	



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 2
 Contractor Section - Contractor Direction

13.6	Earthworks	
13.7	Drainage	
13.8	Maintenance	
13.9	Stream and drainage line crossings	
13.11	Closure and rehabilitation of roads	
13.13	Removal and rehabilitation of bridges, crossings and culverts	
14.	Quarries, borrow pits and fill disposal areas	
14.0	Quarries, borrow pits and fill disposal areas	
15.	Preparation, measurement, grading and extraction of logs	
15.2	Log preparation	
21.	Carting logs	
21.1	Carting logs - general obligations of the driver	
23.	Weather restrictions	
23.0	Weather restrictions	
26.	Sorting and using fuel and servicing machinery	
26.1	Fuel location	
26.2	Fuel precautions	
27.	Camp sites, waste disposal and forest hygiene	
27.1	Camp sites	
27.3	Water points	
27.4	Forests hygiene (weeds, pests and disease)	Washdown of machinery prior to arrival and departure.
27.5	Field Washdown/Cleaning Procedure for Machinery	



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 2
Contractor Section - Contractor Direction

All other action will be conducted as per the Utilisation Procedures, unless outlined in the Coupe Diary by a VicForests Officer.

Habitat Retention Plan

Habitat Description and Marking

As per HCV plan & Operations Map.

Habitat trees will be retained...**Scenario**

- . Outside the harvesting tapes, but within the 'gross coupe boundary'
- . As individual trees along the edge, outside the harvested area
- . As individual trees, scattered throughout the coupes
- . In patch(es)/clump(s) within the harvested area
- . To serve as seed trees also
- . Other requirements

Yes
Yes
Yes
Yes
Yes
Yes

Other requirements

Retention as per HCV Retention plan and Operations map.

* See variation page for marking procedure.

End of Forest Operations Coupe Plan Section 2



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 3
 Contractor Section - Coupe Occupational Health and Safety

Hazard Type	Comments on the identified hazard where the hazard exceeds that normally expected	Hazard adequately addressed within Contractor's Safety Management System?
Was a field-based hazard assessment done?	Yes / No	
Arial Hazard		
Stags	[None]	
Other aerial hazards	Dead limbs progressively drying out. Branch fall increasing with warmer weather as of January 1st 2021.	
Percentage of tress containing a high proportion of dead limbs (i.e. mature-age, psyllid, drought or fire affected)	100 % if > 50% handfall not allowed as main harvest method.	
Percentage of the trees having mature interlocked crowns	20 % if > 50% handfall not allowed as main harvest method.	
Ground Hazard		
Slope	[None]	
Rock	[None]	
Rock Faces	[None]	
Morganers	[None]	
Other Ground Hazards	Hidden burnt stakes within coupe.	
Have any mineshafts been located? If yes, GPS location and include coupe map.	[None]	
Access Roads/Landings		
Grade	[None]	
Width	[None]	
Traffic & Falling Ops	Relatively heavy timber & roading traffic in the general area. Roads to be closed when falling within two tree lengths.	
Access	[None]	



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 3
 Contractor Section - Coupe Occupational Health and Safety

Are there hazardous trees adjacent trees to the roads that should be removed?	Fire killed ash along all roads.	
Fire	[None]	
Hand Falling	[None]	
Other	[None]	
Is there any power lines/cables in or around coupe?	[None]	
Are there neighbours that will need to be notified of operations?	[None]	
Safety Comments		

Additional hazards identified				
<i>Describe hazard</i>	<i>Action Required</i>	<i>Responsible person</i>	<i>Date Required</i>	<i>Complete Y/N</i>

End of Forest Operations Coupe Plan Section 3



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 4
Forester Section - Coupe Management Actions

Issues identified						
1. Situation	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Apiary zone within 1600m	* None found *	Not Present	Not Present	No action required		
Apiary zone within coupe	* None found *	Not Present	Not Present	No action required		
Bicentennial Trail in coupe	Bicentennial Trail in coupe	0.00	0.00	No action required		
Bicentennial Trail within 500m of coupe	Bicentennial Trail with 500m	Not Present	Not Present	No action required		
Fire Fuel Management Zone in coupe	4 - Planned Burn Exclusion Zone	21.97	21.97	Coupe is within Zone 4 - Planned Burning Exclusion Zone (PBEZ)	Natural regeneration post wildfire is anticipated. If regeneration burn is required, approval will be sought from DELWP.	Natural regeneration post wildfire is anticipated. If regeneration burn is required, approval will be sought from DELWP.
Forest Management Zone within 200m	CFP : Code of Forest Practice	Present	Present	Modelled Code of Practice for Timber Production exclusion areas adjacent to coupe boundary.	No action required	
Forest Management Zone within 200m	GMZ : General Management Zone	Present	Present	General Management Zone adjacent to coupe boundary.	No action required	
Forest Management Zone within 200m	PRK : Conservation Parks and Reserves	Present	Present	Coupe adjacent to the Alpine National Park managed by Parks Victoria.	National Park boundary has been located and marked in field using a GPS, compass and hipchain. Boundary has been signed off by Regional Manager prior to harvesting commencement. Supervising Forester has confirmed boundary with Parks Victoria prior to harvesting and completed the Parks Victoria sign-off form.	National Park boundary has been located and marked in field using a GPS, compass and hipchain. Boundary has been signed off by Regional Manager prior to harvesting commencement. Supervising Forester has confirmed boundary with Parks Victoria prior to harvesting and completed the Parks Victoria sign-off form. Boundary sign-off complete 15/03/2021.
Forest Management Zone within 500m	CFP : Code of Forest Practice	Present	Present	Modelled Code of Practice for Timber Production exclusion areas adjacent to coupe boundary.	No action required	
Forest Management Zone within 500m	GMZ : General Management Zone	Present	Present	General Management Zone adjacent to coupe boundary.	No action required	
Forest Management Zone within 500m	PRK : Conservation Parks and Reserves	Present	Present	Coupe adjacent to the Alpine National Park managed by Parks Victoria.	National Park boundary has been located and marked in field using a GPS, compass and hipchain. Boundary has been signed off by Regional Manager prior to harvesting commencement. Supervising Forester has confirmed boundary with Parks Victoria prior to harvesting and completed the Parks Victoria sign-off form.	National Park boundary has been located and marked in field using a GPS, compass and hipchain. Boundary has been signed off by Regional Manager prior to harvesting commencement. Supervising Forester has confirmed boundary with Parks Victoria prior to harvesting and completed the Parks Victoria sign-off form. Boundary sign-off complete 15/03/2021.



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 4
Forester Section - Coupe Management Actions

Issues identified						
1. Situation	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Forest Management Zone within coupe	CFP : Code of Forest Practice	1.03	1.03	"The proposed gross coupe area contains 1 temporary stream , and has 0 ha of >30 degree slope.	All operations to be carried under the prescriptions of the Post Bushfire Timber Recovery Instruction. Harvesting and Roading activities will be conducted in accordance with the Vicforests operating procedures and Code of Practice for Timber Production 2014.	All coupes in fire impacted compartments are classified in the High or Very High water quality risk category. Hydrology features have been identified in the field and marked in accordance with the Post Bushfire Timber Recovery Instruction. Permanent streams, pools and wetlands 40m buffer. Temporary Streams 20m buffer. Drainage Lines 15m filter. Where practical, whilst minimising disturbance, distribution of bark and harvest slash to be utilised in erosion control.
Forest Management Zone within coupe	GMZ : General Management Zone	20.94	20.94	General Management Zone within gross coupe boundary.	All operations to be carried under the prescriptions of the Post Bushfire Timber Recovery Instruction. Harvesting and Roading activities will be conducted in accordance with the Vicforests operating procedures and Code of Practice for Timber Production 2014.	All coupes in fire impacted compartments are classified in the High or Very High water quality risk category. Hydrology features have been identified in the field and marked in accordance with the Post Bushfire Timber Recovery Instruction. Permanent streams, pools and wetlands 40m buffer. Temporary Streams 20m buffer. Drainage Lines 15m filter. Where practical, whilst minimising disturbance, distribution of bark and harvest slash to be utilised in erosion control.
Non-State Forest in coupe	* None found *	0.00	0.00	No action required		
Other situation issues	Other situation issues	[n/a]	Present	Coupe falls within an Alpine grazing lease.	Lessee has been informed of VF harvesting plans.	No further action.
Permanent fire break in coupe	* None found *	0.00	0.00	No action required		
Permanent fire break within 500m of coupe	* None found *	0.00	0.00	No action required		
Private land within 500m	Private property	Not Present	Not Present	No action required		
Private land within coupe	Private property	Not Present	Not Present	No action required		
Recreational hut in coupe	Recreation hut	Not Present	Not Present	No action required		
VF Reserve in coupe	* None found *	0.00	0.00	No action required		
VF Reserve within 500m	* None found *	0.00	0.00	No action required		



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 4
Forester Section - Coupe Management Actions

Issues identified						
1. Situation	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
VF SMA in coupe	GPR Prescription	21.97	21.97	Special Management Area VFSMP71 (Green Patch Retention) located within coupe boundary.	Only dead Ash will be harvested. All operations to be carried under the prescriptions of the Post Bushfire Timber Recovery Instruction. Harvesting and Roding activities will be conducted in accordance with the Vicforests operating procedures and Code of Practice for Timber Production 2014. No green ash to be harvested within VFSMZ.	Only dead Ash will be harvested. All operations to be carried under the prescriptions of the Post Bushfire Timber Recovery Instruction. Harvesting and Roding activities will be conducted in accordance with the Vicforests operating procedures and Code of Practice for Timber Production 2014. No green ash to be harvested within VFSMZ.
VF SMA within 500m	GPR Prescription	207.27	207.27	Special Management Area VFSMP71 (Green Patch Retention) located within 500m of coupe boundary.	No action required	
Walking track in coupe	Walking track	Not Present	Not Present	No action required		
Walking track within 500m of coupe	Walking track	Not Present	Not Present	No action required		
2. Stand	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Allocation Order Stratum	Ash	21.55	21.55	Coupe overlay indicates 21.55 ha of Ash Species within the gross coupe boundary.	Harvest in accordance with the Allocation Order to VicForests and Code of Practice for Timber Production.	Harvest in accordance with the Allocation Order to VicForests and Code of Practice for Timber Production. Only fire killed Ash will be harvested.
Allocation Order Stratum	Mixed Species	0.42	0.42	Coupe overlay indicates 0.42 ha of Mixed Species within the gross coupe boundary.	Harvest in accordance with the Allocation Order to VicForests and Code of Practice for Timber Production.	Harvest in accordance with the Allocation Order to VicForests and Code of Practice for Timber Production. Only fire killed Ash will be harvested.
3. Soil and Water	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Designated Water Catchment within coupe	LAKE HUME NORTHERN SECTION	21.97	21.97	Coupe located within Lake Hume Northern Section Special Water Supply Catchment. Seasonal closures from 1 July - 30 September.	No harvesting to take place between these dates.	No harvesting to take place between these dates.

Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 4
Forester Section - Coupe Management Actions

Issues identified						
3. Soil and Water	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Designated Water Supply Catchment within 500m	LAKE HUME NORTHERN SECTION	185.30	185.30	Coupe located within Lake Hume Northern Section Special Water Supply Catchment. Seasonal closures from 1 July - 30 September.	No harvesting to take place between these dates.	No harvesting to take place between these dates.
Other water issues	Other water issues	[n/a]	Not Present	No action required		
Slope Class within coupe	0-20 Degrees	21.97	21.97	Gross coupe area contains a 21.97ha area of 0-20 slope	All operations to be carried under the prescriptions of the Post Bushfire Timber Recovery Instruction. Harvesting and Roading activities will be conducted in accordance with the Vicforests operating procedures and Code of Practice for Timber Production 2014.	All operations to be carried under the prescriptions of the Post Bushfire Timber Recovery Instruction. Harvesting and Roading activities will be conducted in accordance with the Vicforests operating procedures and Code of Practice for Timber Production 2014.
Water quality risk within coupe	High or Very High Water Quality Risk	[n/a]	Present	High or Very High Water Quality Risk Impact from 2020 bushfires have determined that the overall Water Quality Risk (Soil Erosion category) to be High or Very High within this coupe.	All operations to be carried under the prescriptions of the Post Bushfire Timber Recovery Instruction. Harvesting and Roading activities will be conducted in accordance with the Vicforests operating procedures and Code of Practice for Timber Production 2014.	All coupes in fire impacted compartments are classified in the High or Very High water quality risk category. Hydrology features have been identified in the field and marked in accordance with the Post Bushfire Timber Recovery Instruction. Permanent streams, pools and wetlands 40m buffer. Temporary Streams 20m buffer. Drainage Lines 15m filter. Where practical, whilst minimising disturbance, distribution of bark and harvest slash to be utilised in erosion control.
4. Biodiversity	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Barred Galaxias streams in coupe or within 500m	Barred Galaxias catchment in coupe or within 500m	Not Present	Not Present	No action required		
Old Growth Forest in coupe	* None found	0.00	0.00	No action required		
Old Growth Forest within 500m	* None found	Not Present	Not Present	No action required		
Other biodiversity issues	Other biodiversity issues	[n/a]	Not Present	No action required		



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 4
Forester Section - Coupe Management Actions

Issues identified						
4. Biodiversity	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Other threatened flora	* None found *	Not Present	Not Present	No action required		
Rainforest in coupe	None found	0.00	0.00	No action required		
Rainforest site in coupe	* None found *	0.00	0.00	No action required		
Rainforest site within 500m	Rainforest site of significance	Not Present	Not Present	No action required		
Rainforest within 500m	None found	0.00	0.00	No action required		
Reference Area within 500m of coupe	Reference area	Not Present	Not Present	No action required		
Spotted Tree Frog catchment in coupe		Present	Present	Coupe located within greater Wheeler STF catchment, but not within 1km upstream of known STF sites and not within STF Management Zones.	Construction of stream crossings should be minimised and any new roads should be located at least 50m from any stream unless there are sediment management operations in place to prevent sediments from entering streams.	Construction of stream crossings should be minimised and any new roads should be located at least 50m from any stream unless there are sediment management operations in place to prevent sediments from entering streams. No stream crossings are currently planned or deemed necessary for this coupe.
Spotted Tree Frog catchment within 500m		Present	Present	Coupe located within greater Wheeler STF catchment, but not within 1km upstream of known STF sites and not within STF Management Zones.	No action required	
Spotted Tree Frog in coupe	* None found *	Not Present	Not Present	No action required		
Spotted Tree Frog within 500m	* None found *	Not Present	Not Present	No action required		
Threatened EVC in coupe	* None found *	0.00	0.00	No action required		
Threatened EVC within 500m	* None found *	0.00	0.00	No action required		
Threatened fauna site in coupe	* None found *	Not Present	Not Present	No action required		
Threatened fauna site within 500m of coupe	Petaurus australis: Yellow-bellied Glider	Not Present	Present	Yellow-bellied Glider species observation record within 500m of coupe boundary.	No action required	
Threatened flora site within 500m of coupe	* None found *	Not Present	Not Present	No action required		

Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 4
Forester Section - Coupe Management Actions

Issues identified						
4. Biodiversity	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Threatened Species Observations in coupe	* None found *	Not Present	Not Present	No action required		
Threatened Species Observations in coupe	* None (issue will not be saved)	Not Present	Not Present	No action required		
Threatened Species Observations within 500m of coupe	* None found *	Not Present	Not Present	No action required		
Threatened Species Observations within 500m of coupe	* None (issue will not be saved)	Not Present	Not Present	No action required		
VF Large Trees in Coupe	None found	Not Present	Not Present	No action required		
VF Large Trees within 500m	None found	Not Present	Not Present	No action required		
5. Historical	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Aboriginal Cultural Sensitivity Area in coupe	* None found	0.00	0.00	No action required		
Aboriginal Cultural Sensitivity Area within 500m	Watercourse	7.15	7.15	An Area of Cultural Sensitivity along Thowgla Creek was identified in the overlay analysis process.	Consultation with AV was undertaken during the TRP approval process. No registered Aboriginal Cultural Heritage sites were identified. No restriction to harvesting. No further action.	Consultation with AV was undertaken during the TRP approval process. No registered Aboriginal Cultural Heritage sites were identified. No restriction to harvesting. No further action.
Historic areas in coupe	* None found *	Not Present	Not Present	No action required		
Historic areas within 500m	* None found *	Not Present	Not Present	No action required		
Historic sites in coupe	Historic site	Not Present	Not Present	No action required		
Historic sites within 500m	Historic site	Not Present	Not Present	No action required		
Historic tramway site in coupe	Historic tramway	Not Present	Not Present	No action required		
Historic tramways site within 500m of coupe	Historic tramway	Not Present	Not Present	No action required		



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 4
Forester Section - Coupe Management Actions

Issues identified						
5. Historical	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Other historical issues	Other historical issues	[n/a]	Not Present	No action required		
6. Landscape	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Foreground issues (0-500m)	* None found *	0.00	0.00	No action required		
Landscape Issues in coupe	* None found *	0.00	0.00	No action required		
Middleground issues (500m-6.5k)	MOUNT_PINNIBAR_p Middleground	12.73	12.73	Overlay detected 12.73ha of coupe is within 500 m - 6.5km of Mt Pinnibar.	The coupe is not visible from this location due to topography and standing forest.	The coupe is not visible from this location due to topography and standing forest.
Other landscape issues	Other landscape issues	[n/a]	Not Present	No action required		
Outer issues (6.5k - 12km)	* None found *	0.00	0.00	No action required		
7. Research	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Other research issues	Other research issues	[n/a]	Not Present	No action required		
Permanent Growth Plot buffer in coupe	Permanent Growth Plot buffer	Not Present	Not Present	No action required		
8. Weeds, Pests & Disease	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Pests and Disease	None identified	[n/a]	None identified	No Further Action		



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 4
Forester Section - Coupe Management Actions

Issues identified						
8. Weeds, Pests & Disease	Value	Identified by spatial overlay as	Identified during manual check as	Value Description	How the value will be managed	Management Action Taken or Prescription Applied
Weeds	Blackberry	[n/a]	Scattered	A scattered occurrence of Blackberry was observed within the gross coupe area and/or surrounding areas during field inventory. It is considered regionally controlled .	Machinery to be washed down before departing area	Machinery to be washed down before departing Dunstans Road salvage area.
<i>End of Forest Operations Coupe Plan Section 4</i>						



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 5
Contractor Section - Harvesting Commencement & Completion Declarations

Harvesting commencement declaration	Contractor/HTL Initial	VicForests Initial
▪ I have received a copy of the Forest Coupe Plan and a copy of the Utilisation Procedures.		
▪ I have discussed this Forest Coupe Plan with an Officer of VicForests and understand it.		
▪ I will ensure that this operation is conducted in accordance with the Forest Coupe Plan, the Utilisation Procedures and the Occupational Health and Safety Act.		
▪ I will ensure that all operators working on this coupe are aware of their responsibilities under this Forest Coupe Plan.		
▪ I will ensure that all operators hold a current FOLS with all appropriate endorsements prior to them commencing work on the coupe.		
▪ An identification of hazards associated with this coupe was conducted in accordance with the Industry Standard: Safety in Forestry Operations (Harvesting and Haulage) 2007 and the Occupational Health and Safety Act 2004.		
▪ The Contractor/HTL acknowledges that it is their responsibility to identify the appropriate controls for all identified hazards. VicForests acknowledges that the Contractor/HTL has a hazard control plan that identifies all addresses all identified hazards.		
▪ Landing(s) location has been agreed to by VicForests and the Contractor/HTL		
▪ Location/selection of retained trees has been agreed to by VicForests and the Contractor/HTL		
▪ I have been briefed on the identification and habitat retention strategies put in place to manage Biodiversity Values identified in this coupe as outlined in the HCV summary and retention plan		
Contractor / HTL _____	Signed _____	Date _____
Sanctioned By VicForests Officer _____	Signed _____	Date _____

The names and FOLS numbers of the crew working on this Harvest Unit are:

HTL _____	FOLS No. _____	
Log Grader _____	FOLS No. _____	Hammer No. _____
Crew Member _____	FOLS No. _____	
Crew Member _____	FOLS No. _____	
Crew Member _____	FOLS No. _____	
Crew Member _____	FOLS No. _____	



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 5
Contractor Section - Harvesting Commencement & Completion Declarations

Provisional Clearance Declaration

This coupe cannot be completed until a later date. This provisional clearance has been granted to the Logging Team Leader subject to the coupe being left in an approved condition.

I acknowledge that if directed by VicForests, I will return to carry out any actions that result from the temporary clearance assessment.

Contractor/HTL _____

Signed _____

Date _____

This harvesting operation has been completed to the satisfaction of VicForests.

VicForests Officer _____

Signed _____

Date _____

Harvesting Re-commencement Declaration

- I have received a copy of the Forest Coupe Plan and a copy of the Utilisation Procedures.
- I have discussed the Forest Coupe Plan with an Office of VicForests and understand it.
- A reassessment of the hazards and controls associated with the coupe was conducted in accordance with the Industry Standard: Safety in Forestry Operations (Harvesting and Haulage) 2007 and the Occupational Health and Safety Act 2004.
- I will ensure that this operation is conducted in accordance with the Forest Coupe Plan, the Utilisation Procedures and the Occupational Health and Safety Act.
- I will ensure that the operators working on this coupe are aware of their responsibilities under the Forest Coupe Plan.
- I will ensure that all operators hold a current FOLS with all appropriate endorsements prior to commencing work on the coupe.

Contractor/HTL _____

Signed _____

Date _____

Witnessed by
VicForests Officer _____

Signed _____

Date _____



Harvest Unit 699-518-0005-A - Photo Finish
FOREST OPERATIONS COUPE PLAN - SECTION 5
Contractor Section - Harvesting Commencement & Completion Declarations

Final Completion and Clearance Declaration

This clearance to leave the coupe has been granted to the Contractor / Logging Team Leader.

I acknowledge that if directed by VicForests, I will return to carry out any actions that result from the final clearance assessment.

Contractor/HTL _____

Signed _____

Date _____

This coupe has been completed to the satisfaction of VicForests.

VicForests Officer _____

Signed _____

Date _____

** record in Cengea*

End of Forest Operations Coupe Plan Section 5